

ASSEMBLY, No. 1730

STATE OF NEW JERSEY

219th LEGISLATURE

PRE-FILED FOR INTRODUCTION IN THE 2020 SESSION

Sponsored by:

Assemblywoman ANGELA V. MCKNIGHT

District 31 (Hudson)

Assemblyman NICHOLAS CHIARAVALLOTI

District 31 (Hudson)

Assemblyman JAMEL C. HOLLEY

District 20 (Union)

Co-Sponsored by:


**Assemblywoman Chaparro, Assemblyman Verrelli, Assemblywomen
Reynolds-Jackson, Murphy and Speight**

SYNOPSIS

Requires lobby security for certain senior citizen high-rise buildings in areas with high violent crime rates.

CURRENT VERSION OF TEXT

Introduced Pending Technical Review by Legislative Counsel.



1 **AN ACT** concerning senior citizen security in certain high rise
2 buildings and amending P.L.1967, c.76 and P.L.1983, c.154.

3

4 **BE IT ENACTED** *by the Senate and General Assembly of the State*
5 *of New Jersey:*

6

7 1. Section 7 of P.L.1967, c.76 (C.55:13A-7) is amended to read
8 as follows:

9 7. The commissioner shall issue and promulgate, in the manner
10 specified in section 8 of P.L.1967, c.76 (C.55:13A-8), such
11 regulations as the commissioner may deem necessary to assure that
12 any hotel or multiple dwelling will be maintained in such manner as
13 is consistent with, and will protect, the health, safety and welfare of
14 the occupants or intended occupants thereof, or of the public
15 generally.

16 Any such regulations issued and promulgated by the
17 commissioner pursuant to this section shall provide standards and
18 specifications for such maintenance materials, methods and
19 techniques, fire warning and extinguisher systems, elevator
20 systems, emergency egresses, and such other protective equipment
21 as the commissioner shall deem reasonably necessary to the health,
22 safety and welfare of the occupants or intended occupants of any
23 units of dwelling space in any hotel or multiple dwelling, including
24 but not limited to:

- 25 (a) Structural adequacy ratings;
26 (b) Methods of egress, including fire escapes, outside fireproof
27 stairways, independent stairways, and handrails, railings, brackets,
28 braces and landing platforms thereon, additional stairways, and
29 treads, winders, and risers thereof, entrances and ramps;
30 (c) Bulkheads and scuttles, partitions, walls, ceilings and floors;
31 (d) Garbage and refuse collection and disposal, cleaning and
32 janitorial services, repairs, and extermination services;
33 (e) Electrical wiring and outlets, and paints and the composition
34 thereof;
35 (f) Doors, and the manner of opening thereof;
36 (g) Transoms, windows, shafts and beams;
37 (h) Chimneys, flues and central heating units;
38 (i) Roofing and siding materials;
39 (j) Lots, yards, courts and garages, including the size and
40 location thereof;
41 (k) Intakes, open ducts, offsets and recesses;
42 (l) Windows, including the size and height thereof;
43 (m) Rooms, including the area and height thereof, and the
44 permissible number of occupants thereof;
45 (n) Stairwells, skylights and alcoves;

EXPLANATION – Matter enclosed in bold-faced brackets **[thus]** in the above bill is
not enacted and is intended to be omitted in the law.

 Matter underlined thus is new matter.

- 1 (o) Public halls, including the lighting and ventilation thereof;
2 (p) Accessory passages to rooms;
3 (q) Cellars, drainage and air space;
4 (r) Water-closets, bathrooms and sinks;
5 (s) Water connections, including the provision of drinking and
6 hot and cold running water;
7 (t) Sewer connections, privies, cesspools, and private sewers;
8 (u) Rain water and drainage conductors;
9 (v) Entrances and ramps; **【and】**
10 (w) Presence of lead-based paint hazards in multiple dwellings
11 and in single-family and two-family dwellings, exclusive of owner-
12 occupied dwelling units, subject to P.L.2003, c.311 (C.52:27D-
13 437.1 et al.). In a common interest community, any inspection fee
14 for and violation found within a unit which is solely related to this
15 subsection shall be the responsibility of the unit owner and not the
16 homeowners' association, unless the association is the owner of the
17 unit; and
18 (x) Security of residents in lobbies and interior common areas.
19 (cf: P.L.2007, c.251, s.5)
20

21 2. Section 2 of P.L.1983, c.154 (C.55:13A-13.1) is amended to
22 read as follows:

23 2. a. Any retirement community as defined in the "Retirement
24 Community Full Disclosure Act," P.L.1969, c.215 (C.45:22A-1 et
25 seq.) shall be exempt from inclusion in the definition of multiple
26 dwellings contained in paragraph (k) of section 3 of P.L.1967, c.76
27 (C.55:13A-3), provided that the retirement community complies
28 with the basic standards relating directly to resident physical safety
29 and to fire safety which are established for its buildings by
30 subsection d. of this section and by rule or regulation of the
31 commissioner and provided further, that the retirement community
32 files with the commissioner, at least once every five years, as
33 evidence of a satisfactory self-inspection, a completed checklist,
34 which shall be provided by the commissioner, of items established
35 under the fire safety regulations. The retirement community shall
36 also file a certification, from the municipal fire protection subcode
37 official or an equally competent person selected and paid by the
38 municipality in which the retirement community is located, that the
39 self-inspection has been properly carried out. A fee schedule for
40 certification may be established by the municipality providing for a
41 charge of up to \$8.00 per dwelling unit for each of the first 100
42 units inspected and up to \$5.00 per unit for each unit inspected
43 thereafter.

44 b. The commissioner may require common area smoke
45 detectors in buildings, and the retirement community may utilize
46 detector units which are either (1) of the alternating current (AC)
47 constantly active electric circuit type, which cannot be deactivated
48 by the operation of any interconnected switching device and which

1 comply with the latest NJPA-70 (National Electrical Code)
2 requirements or (2) of the battery-powered single station type. The
3 owners of each unit utilizing any common area shall be jointly
4 responsible for inspecting the detector unit in the common area and
5 for ensuring that its battery is inspected periodically and replaced at
6 least annually.

7 c. If the municipality determines, as a result of the most recent
8 self-inspection of any building or unit as required by this
9 amendatory and supplementary act, that any building or unit does
10 not comply with the provisions of this amendatory and
11 supplementary act and regulations promulgated thereunder, then the
12 municipality shall issue to the nonprofit corporation a written notice
13 stating the manner in which a building or unit does not comply with
14 this amendatory and supplementary act or regulations promulgated
15 thereunder. The notice shall fix a date, not less than 60 days nor
16 more **【then】** than 180 days, upon which a building or unit shall
17 comply with the provisions of this amendatory and supplementary
18 act and regulations promulgated, thereunder. If building or unit
19 does not comply with the provisions of this amendatory and
20 supplementary act and regulations promulgated, on or before the
21 date fixed in the notice, the municipality shall notify the
22 commissioner, who shall enforce the provisions of P.L.1967, c.76
23 (C.55:13A-1 et seq.) against the nonprofit corporation or the unit
24 owner thereof, based on their respective liabilities as contained in
25 the nonprofit corporation's master deed, bylaws, and rules and
26 regulations.

27 d. (1) In every municipality for which the violent crime rate
28 exceeds six per 1,000 persons according to the average of the three
29 most recent Uniform Crime Reports issued by the New Jersey State
30 Police, the lobby of a retirement community that is a multiple
31 dwelling consisting of at least 50 dwelling units shall have 24-hour
32 security monitoring. In municipalities for which the violent crime
33 rate is six or less per 1,000 persons according to the average of the
34 three most recent Uniform Crime Reports issued by the New Jersey
35 State Police, the commissioner may require lobby or interior
36 common area security monitoring upon evidence of persistent
37 criminal activity against residents in the building. The security
38 monitoring required by this subsection shall be accomplished
39 through the use of video surveillance cameras operated 24 hours a
40 day, trained on and recording all building exits and entrances, as
41 well as any common areas, including parking lots, where criminal
42 incidents have occurred within the past 12 months. If the multiple
43 dwelling consists of 75 dwelling units or more, then the building
44 shall also be monitored 24 hours a day by the on-site security guard
45 or guards. The recordings of the video surveillance cameras shall
46 be maintained for at least 60 days. A licensed security guard shall
47 be a uniformed employee of a licensed security officer company or
48 a uniformed special police officer of the municipality, and shall

1 comply with the requirements as set forth in the "Security Officer
2 Registration Act," P.L.2004, c.134 (C.45:19A-1 et seq.) when
3 applicable.

4 The security standards set forth in this subsection are minimum
5 standards, and shall not prevent any municipality from enacting
6 greater security standards.

7 (2) The Commissioner of Community Affairs, in consultation
8 with the Attorney General, shall annually notify each retirement
9 community that is a multiple dwelling and is located in a
10 municipality for which the violent crime rate exceeds six per 1,000
11 persons according to the three most recent Uniform Crime Reports
12 issued by the New Jersey State Police, of its lobby security
13 requirement pursuant to this subsection.

14 (cf: P.L.1983, c.154, s.2)

15
16 3. This act shall take effect immediately, but, except for the
17 promulgation of rules, regulations, and notices, shall remain
18 inoperative until the first day of the seventh month next following
19 enactment.

20 21 22 STATEMENT

23
24 This bill requires the owners of senior citizen high-rise buildings
25 having 50 units or more to provide 24-hour security if the building is
26 located in a municipality with a violent crime rate exceeding six per
27 1,000 persons, according to the average of the three most recent
28 Uniform Crime Reports issued by the New Jersey State Police.

29 The Commissioner of Community Affairs, in consultation with the
30 Attorney General, would be responsible for annually notifying the
31 owners of those buildings of their security obligations under the law.
32 The bill requires buildings consisting of 75 dwelling units or more to
33 meet their security obligation through 24-hour monitoring by on-site
34 security guards. If the building consists of at least 50, but fewer than
35 75 dwelling units, then the security obligation may be satisfied through
36 the use of video surveillance cameras operated 24 hours a day,
37 recording all building exits and entrances, as well as any common
38 areas, including parking lots, where criminal incidents have occurred
39 within the past 12 months. The bill enables the Commissioner of
40 Community Affairs to order a building owner in a municipality with a
41 violent crime rate of six or less per 1,000 persons to provide security in
42 the lobby or other common area upon evidence of persistent criminal
43 activity against residents in the building.

44 The bill also gives the commissioner the authority to issue
45 regulations concerning the security of residents in lobbies and interior
46 common areas of hotels and multiple dwellings in general. The bill
47 contains a delayed operative date of approximately six months to allow
48 time for the promulgation of rules, regulations, and notices.